

# HIWRAP Status Update

Submitted by **gheymsfield** on Mon, 09/20/2010 - 07:46

- **HIWRAP**

Flight Date:

Saturday, September 18, 2010

Previous flights collected good data on 2 out of 4 channels (one beam at Ku and Ka-band) due to a high noise level on 2 channels. New firmware was uploaded to the digital receiver FPGA's to correct this noise problem so that the other two channels (2 frequencies and 2 incidence angles) are fully functional. This will be tested on next flight. Otherwise, system has been fully functional on all previous flights.

Status:

Green